

## TABLE OF CONTENTS

CHAPTER	TITLE	PAGE
	<b>DECLARATION</b>	<b>ii</b>
	<b>DEDICATION</b>	<b>iii</b>
	<b>ACKNOWLEDEMENTS</b>	<b>iv</b>
	<b>ABSTRACT</b>	<b>v</b>
	<b>ABSTRAK</b>	<b>vi</b>
	<b>TABLE OF CONTENTS</b>	<b>vii</b>
	<b>LIST OF TABLES</b>	<b>xi</b>
	<b>LIST OF FIGURES</b>	<b>xii</b>
	<b>LIST OF APPENDICES</b>	<b>xvii</b>
<b>1</b>	<b>INTRODUCTION</b>	<b>1</b>
	1.1 Background	1
	1.2 Problem Statement	2
	1.3 Aim and Objectives	3
	1.4 Scope	3
	1.5 Significance of the Study	4
	1.6 Research Methodology	4
	1.7 Layout of Thesis	5
<b>2</b>	<b>LITERATURE REVIEW</b>	<b>7</b>
	2.1 Introduction: The Need and Benefits of ‘Smart Structures’ Application	7
	2.1.1 The Need	7
	2.1.2 The Benefits	9
	2.2 Definition of ‘Smart Structures’	14

2.3	Smart Bridge Monitoring Technologies	15
2.4	Smart Bridge Technology Systems	15
2.4.1	Fiber Optic Sensor (FOS) based Monitoring System	16
	2.4.1.1 SOFO Monitoring System	16
	2.4.1.2 OSMOS Monitoring System	18
2.4.2	Integrated, Internet-based On-line Monitoring System	20
	2.4.2.1 On-line Alerting of Structural Integrity and Safety (OASIS) System	21
2.4.3	Real-time Kinematic GPS-based Monitoring System	24
2.4.4	Robotic Total Station-based Monitoring System	27
	2.4.4.1 Deformation Monitoring System (Leica Geosystems Inc.)	31
2.4.5	Acoustic Emission-based Monitoring System	31
	2.4.5.1 SoundPrint®	31
	2.4.5.2 Sensor Highway II System <sup>TM</sup>	34
2.4.5	Analysis of Structural Responses-based Monitoring	35
	2.4.5.1 Ambient Vibration-based Monitoring (AVM)	36
	2.4.5.1.1 BRIMOS®	36
2.5	Other Smart Bridge Technology Components	38
2.5.1	Sensing Technologies	38
	2.5.1.1 Fiber Optic Sensors (FOS)	39
	2.5.1.2 Smart Sensors	40
	2.5.1.2.1 SMART FODS	40
	2.5.1.2.2 Fiber Bragg (FBG) Grating Sensors	41
	2.5.2 Embeddable Corrosion Sensors	42
	2.5.3 Micro-electrochemical Sensors (MEMS)	43

	2.5.4 Piezoelectric Systems	43
	2.5.5 Wireless Sensors	44
	2.5.6 Smart Bridge Bearings	45
2.6	Data Acquisition and Processing	46
	2.6.1 SmartComposite™ Software	47
2.7	Wireless Communication	47
2.8	Data Processing and Management	50
	2.8.1 Artificial Neural Networks (ANNs)	50
	2.8.2 Some Examples of Bridge Monitoring Projects	51
2.9	Summary	55
<b>3</b>	<b>DEVELOPMENT OF SMART BRIDGE TECHNOLOGIES DATABASE</b>	<b>56</b>
3.1	Data and Information	56
3.2	The Database and Database Management System (DBMS)	57
	3.2.1 Database	57
	3.2.2 Database Management System (DBMS)	57
	3.2.3 Relational Database and the Relational Database Management System (RDMS)	58
3.3	The Merits of Microsoft® Access™ 2007	59
	3.3.1 Introduction	59
	3.3.2 Its Merits	60
3.4	Identification of Monitoring Metrics	60
	3.4.1 Corrosion of Steel	61
	3.4.2 Fracture in Steel	61
	3.4.3 Loose and/or Deficient Connections	62
	3.4.4 Deformation	63
	3.4.5 Cracks in Reinforced and Prestressed Concrete	63
	3.4.6 Wire Breakage	64
	3.4.7 Spalling	64
	3.4.8 Corrosion of Reinforcement	64
	3.4.9 Wear and Abrasion	65
	3.4.10 Material Deterioration	65

3.4.11	Delamination	66
3.4.12	Abnormal Vibration / Deflection	67
3.4.13	Tilt / Settlement	67
3.4.14	Erosion / Scouring	68
3.4.14.1	Case Study	68
3.4.15	Impact Damage	69
3.4.15.1	Case Studies	69
3.4.16	Abnormal Spacing at Bridge Joint	71
3.4.17	Abnormal Movement	71
3.5	Database Design using Microsoft® Access™ 2007	72
3.6	User Instructions for Smart Bridge Technology Database	77
3.7	Examples on the Use of Database	79
<b>4</b>	<b>CONCLUSIONS AND RECOMMENDATIONS</b>	<b>81</b>
4.1	General	81
4.2	Outcome of the Study	82
4.2.1	Increase Awareness on Smart Structures and Associated Technologies	82
4.2.2	Consolidated Information on Smart Monitoring Technology Providers	82
4.2.3	Analysis of Selected Case Studies	83
4.2.4	Development of Database on Smart Bridge Monitoring Technologies	85
4.3	Recommendations for Future Works	86
	<b>REFERENCES AND BIBLIOGRAPHIES</b>	<b>87</b>
	Appendices A - B	<b>92-127</b>

**LIST OF TABLES**

<b>TABLE NO.</b>	<b>TITLE</b>	<b>PAGE</b>
2.1	Static and dynamic damage factors.	54
2.2	Sensor sensitivity for different number of cracks.	54
3.1	Damage Table Records.	74
3.2	SmartComponents Table Records	74

## LIST OF FIGURES

<b>FIGURE NO.</b>	<b>TITLE</b>	<b>PAGE</b>
2.1	Scenes of I-35W bridge collapse.	8
2.2	One section of I-35W bridge collapse.	8
2.3	Another view of I-35W bridge collapse	8
2.4	Close up view of I-35W bridge collapse.	8
2.5	Wireless strain sensing installed at the Ben Franklin Bridge	10
2.6	The Ben Franklin Bridge spans the Delaware Rivers.	11
2.7	Aerial view of Hall's Harbour.	12
2.8	Schematic of the E. 12th St. Bridge SHM system.	13
2.9	High Performance Steel Girder Incorporated in East 12th Street Bridge over I-235 in Des Moines, Iowa.	14
2.10	SOFO monitoring system.	17
2.11	Surface mounted SOFO sensor measuring flexure in the beam.	17
2.12	SOFO sensor mounted to measure shear	17

	strain.	
2.13	OSMOS system schematic.	19
2.14	‘Dashboard’ display of measurement results.	19
2.15	Portage Creek Bridge SHM web page integrating sensing data and web camera.	21
2.16	The Real-Time monitoring system flow diagram	22
2.17	OASIS System installed at Namahe Bridge, Korea.	23
2.18	Namahe Bridge, Korea: Dynamic sensor location.	23
2.19	Layout of the GPS monitoring system: one base station at the Finger Pier (PSA Building), two ‘rover’ stations on the Republic Plaza building.	26
2.20	Model for on-line monitoring.	26
2.21	Testing tall span.	27
2.22	Leica TCA 2003 set up for Load Testing.	28
2.23	Reference point.	28
2.24	Target (Prism) on bridge.	28
2.25	The oscillator 2D and the standard prism positioned on the industrial pillar.	30
2.26	Rio Pelotas Bridge.	31
2.27	Monitoring points.	31
2.28	Acoustic Emission	32

2.29	Sensors attached to cable.	33
2.30	Data acquisition system.	33
2.31	Sensor Highway II System <sup>TM</sup> .	34
2.32	Measurement grid of accelerometers along the bridge structures.	37
2.33	BRIMOS® Recorder applied for analyzing dynamic structural behaviour of bridge deck.	38
2.34	BRIMOS® Recorder applied for analyzing dynamic behaviour of a stayed cable.	38
2.35	Optical Strand	40
2.36	Optically encoded sensors.	41
2.37	Embedded Corrosion Instrument (EC-1).	42
2.38	Self powered piezoelectric.	44
2.39	Extensive bulging to elastomeric bearing pad	46
2.40	Abnormal displacement of elastomeric bearing pad.	46
2.41	Walking of bearing pads at viaduct, Middle Ring Road II.	46
2.42	Deformation of rubber bearing.	46
2.43	Real-time data acquisition and simultaneous wireless transmission of buffered sensor data.	48
3.1	Widespread medium level of corrosion to steel and buckle plates.	61
3.2	Very severe corrosion to steel beam. Total loss of steel section at the web.	61
3.3	Fracture at splice connection.	62
3.4	Loose connections.	62



3.5	Deformation of buckle plate.	63
3.6	Very severe crack at pile columns due to bending.	63
3.7	Very severe spalling of concrete deck slab.	64
3.8	Very severe corrosion of exposed reinforcement with heavy rusting and pitting.	65
3.9	Medium level wear and abrasion of pile column.	65
3.10	Concrete deterioration of post-tensioned beam.	66
3.11	Severe delamination at deck soffit due to corrosion of reinforcement.	67
3.12	Abnormal deflection of steel girder.	67
3.13	Abnormal deflection with vertical sag at top chord.	67
3.14	Differential settlement of pier.	68
3.15	Single span steel plate bridge failed due to scouring of abutment.	69
3.16	Badly-damaged piles after collision at Kuala Kedah Bridge.	70
3.17	Partial failure of pedestrian bridge.	71
3.18	Very severe cracking at buried joint.	71
3.19	Movement of bridge pier from its original position.	72
3.20	Company Entity and Attributes	73
3.21	Product Entity and Attributes.	73
3.22	Damage Entity and Attributes.	73
3.23	Entities Relationships.	76
3.24	Splash Screen	77

3.25	Main Menu	77
3.26	Monitoring Option Menu	78
3.27	Abnormal Deflection Damage Description Menu.	78
3.28	Record	79

**LIST OF APPENDICES**

<b>APPENDIX</b>	<b>TITLE</b>	<b>PAGE</b>
A	Companies and Products Record	93
B	Smart Bridge Technologies Database Examples	100